OFFICE OF THE MARION COUNTY SURVEYOR SECTION RECORD CORNER SECTION ______30__TOWNSHIP ____17__ RANGE __3_ DATE: ____9-21-05 PARTY CHIEF: Wilcoxen Line of 75th St. 7500 N CREW: ≥ TYPE OF MARKER: Harrison METHOD OF ESTABLISHMENT: ___ County: 5-30-00 420 IN. S.P.C. E ZONE NAD '83 NAME: 17033005 N: 515415.5425(m) 51676.8552(m) E: NDTE: This corner position represents a title corner and may not necessarily be in the position of the Record corner. 1. 5. 15930' 2. Section Line 7500 N 3. Crooked Creek golf course

A survey by Wm. P. Smith on November 26,27 & 28,1886 called no stone but witness: 24" oak stump N 7 E 75 links, 20" oak N 30 W 8 links per Pike Township Legal Survey Book pg. 16. MCSO 70's called a rebar. Cripe established this corner per Job#81338-00000 and called a rebar. Wilcoxen 6-16-95 called a rebar. A 4"x4" concrete monument fd 0.35' S of this corner. Excavated by Wilcoxen 6-19-95 and Harrison set replacing rebar. Re-tied 5-25-00. Re-tied 9-21-05 by Wilcoxen.

170.33005		
REF.	DISTANCE	DESCRIPTION
1	23.61"	Mag nail w/bw W @wooden fence post
2.	52.57	NW corner of IPI power box
3.	29.27'	Cut 'x' N rim of sewer manhole
4.	56.81	NW corner wooden frame pump house
5.	15.9.30'	NF corner of metal ent/exit bldg.
	L	